SAFETY RECOMMENDATION SR16-00177

Details

Synopsis	On September 30, 2016 a Beechcraft B1900C aircraft, operated by Southern Air Charter Company Limited, a Bahamas Air Operator Certificate holder was involved in an occurrence at Deadman's Cay Airport, Long Island, Bahamas while on a domestic, commercial air transport, scheduled flight.
	N376SA a BE1900 aircraft with a crew of two, and nine passengers, landed on runway 09 with the gear in the retracted position. The captain reported that 10 miles from landing, when the aircraft flaps were selected to the approach position for landing, at this point he realized that the flaps were not working. He further stated that he elected to continue the approach and prepare for a no-flaps landing.
	The performance charts for the aircraft were consulted and preparations were made for the landing. However, upon touchdown, the gears retracted causing the aircraft to land on its belly. No injuries were reported to occupants of the aircraft.
Recommendation	The Air Accident Investigation Department recommends that the Bahamas Civil Aviation Authority Re-examine both airmen involved to ascertain their fitness to hold their respective licenses b) Review check airman authorization granted to airman involved in the accident.
Original Recommendation Transmittal Letter	12-15-2016 Keith 12-14-2016 H. Safety Tracking Major N376SA MYLD.Adderley N376SA MY (SI-00177).pdf
Overall Status	Closed – Unacceptable Action / No Response Received ¹
Location	Deadmans Cay, Long Island, Bahamas
Accident Number	A16-000010
Accident Report	Gear Up Landing
Accident Date	30 th September, 2016
Issue Date	5 th October, 2016
Date Closed	13 th May, 2020
Addressee(s)	Mr. Keith Major – Director (Acting)
Addressee(s) Response	Closed – No Response Received

Safety Recommendation History

From	AAIA
То	BCAA
Date	5 th October, 2016
Response	

¹ Closed – Unacceptable Action / No Response Received – No response to the recommendation was ever received.